

PRODUCT DETAILS



917396

Expansion Valve



POP: B

Per Car: 1

CHECK YOUR FIT

+ Add to Saved List

Part Specifications

Description: Expansion Valves

Tonnage: 2.000

Warranty: 120 days

O-Ring C Number/Desc: 900210 / Green O-Ring

O-Ring D Number/Desc: 900209 / Green O-Ring

O-Ring D Quantity: 1
O-Ring B Number/Desc: 900208 / Green O-Ring
Suc Out Trd: 7/8" - 18
O-Ring B Quantity: 1
Suc Out Gender: Female
Mount Hole Qty: 2
O-Ring A Number/Desc: 900206 / Green O-Ring
O-Ring A Quantity: 1
Meets / Exceeds OEM?: Yes
O-Ring C Quantity: 2
Liquid Inlet Gender: Female
Liquid Inlet Size: No. 6
Liquid Inlet Style: FIO
Liquid Inlet Thread: 5/8 - 18
Liquid Inlet Type: Insert O-Ring
Liquid Outlet Gender: Female
Liquid Outlet Size: No. 8
Liquid Outlet Thread: 3/4" - 18
Material: Aluminum
Style: w/o Solenoid
Suction Inlet Gender: Female
Suction Inlet Size: No. 10
Suction Inlet Thread: 7/8" - 18
Suction Outlet Size: No. 10
Super Heat: 8.000
Switch Included?: Not Included
Type: Block Type
Liquid Outlet Style: FIO
Liquid Outlet Type: Insert O-Ring
Suction Inlet Style: FOR
Suction Inlet Type: O-Ring

Suction Outlet Style: FIO
Suction Outlet Type: Insert O-Ring
Color: Aluminum

Features & Benefits

Our products are engineered and tested to provide years of trouble free operation. Backed by over 50 years of mobile a/c experience, fix it once and fix it right with Everco Heavy Duty.

- Our in-house research & development center utilizes the latest software and precise measuring equipment to ensure product quality. Our expansion devices are specifically calibrated for optimum cabin comfort for both the driver and passengers.
 - Engineered to meet or exceed O.E. fit, form and function requirements, our products contain high quality components for long lasting performance. O-rings, gaskets, and seals are included for each application specific replacement for ease of installation.
 - Each TXV has a unique specification for tonnage, superheat and maximum operating pressure (MOP) based on the specific system. Some A/C performance issues can be traced back to an incorrect valve as a result of misapplication or low quality manufacturing.
 - Precision machined ports
-

Part Type (Category)

Expansion Valves

For Catalog assistance: 1-866-502-0068

[Back to Top](#)
